
Drum Disposal Area Cook County ILD 934791681 SF/HRS



Confidential Material May be Enclosed

CERCLA Preliminary Assessment Report

for

Drum Disposal Area

ILD984791681

INDEX

Section 1 Executive Summary Bibliography

Section 2 EPA Form 2070-12
"Potential Hazardous Waste Site Preliminary Assessments"

Section 3 Maps
State Map
Vicinity Map
Site Map
Site Topography
4-Mile Radius Map
15-Mile Surface Water Route Map

Section 4 Photographs
1965 Aerial Photograph
1988 Aerial Photograph
Photograph Location Map
Site Reconnaissance Photographs

Section 5 Supporting Documentation and References

SECTION 1 EXECUTIVE SUMMARY

EXECUTIVE SUMMARY

The Drum Disposal Area was placed on the Comprehensive
Environmental Response, Compensation and Liability
Information System (CERCLIS) August 29, 1990 as a result of a
request made by the Illinois Environmental Protection Agency.
This request was the result of information received from
officials of the Village of Orland Park concerning leaking
barrels at the site. The site is also listed on CERCLIS under
the name Southwest Highway Drums.

The Drum Disposal Area is located approximately one mile southwest of the Village of Orland Park at the northeast corner of Southwest Highway and 179th Street in Cook County, Illinois. Traditionally a rural setting, this area has more recently started undergoing development as more residential and commercial sites have moved into the area. The site is currently bordered to the north/north-west by Southwest Highway (U.S. Route 6) beyond which lies a recently developed residential area. To the west of the site lies a cornfield, and to the south is 179th Street beyond which lies a transportation project under development. The site is bordered to the east by Marley Creek and the Norfolk and Western Railroad.

According to records at the Orland Township Assessor's Office, the site is currently owned by Prairie Material

Sales, Incorporated, a concrete foundry company in Bridgeview, Illinois. According to Jerry Krozel of Prairie Material Sales, Incorporated, the company purchased the property in the mid-1970's. A 1972 plat map shows the site belonging to S.M. Shively. Local residents state the property has remained vacant for many years. A 1965 aerial photograph indicates the site was vacant at that time, but later photographs (1976, 1988) show filling activity at the site. According to information received from U.S. Environmental Protection Agency records, the site consisted of construction and demolition fill and contained several large, empty concrete batch tanks, along with drums.

Illinois Environmental Protection Agency records indicate that the IEPA became involved with the site in June of 1989 when a complaint was received from an official of the Orland Park Planning Department. According to the complainant, drums were being disposed of in a wetland area, and some drums were leaking a "melted qum"-like material.

The U.S. Environmental Protection Agency became involved with the site in May of 1989 when that agency received a complaint alleging that illegal dumping and filling of wetlands were occurring at the site. During investigation of the complaint by U.S. EPA's Emergency Response Section and the Technical Assistance Team, approximately 42 rusted, leaking drums were discovered on-site. Also found on-site were five empty 10,000

to 15,000 gallon tanks, four empty 500 to 1000 gallon tanks and scrap metal. Some partially buried drums were also found on-site. At this time samples were collected from five of the drums and from stained surface soil. Analytical results of the samples showed two of the drum samples to be ignitable. Soil samples revealed the presence of acetone at 2700 parts per million (ppm), methyl ethyl ketone at 13,000 ppm, toluene at 14,000 ppm and total xylenes at 4,700 ppm.

Following these discoveries an Administrative Order by
Consent was prepared by USEPA, in which Prairie Material
Sales agreed to undertake and complete emergency removal
activities at the site. In August of 1989 the USEPA tasked
the Technical Assistance Team (Weston - Major Programs
Division) to monitor the removal action.

According to a letter from Weston to USEPA, removal activities began at the site June 17, 1989. During removal, drums were sampled, overpacked and removed. Soil was excavated from the drum area and a composite soil sample was collected. The analytical results of this sample are shown below.

methylene chloride	462	ppb
acetone	4010	ppb
2-butanone	262(J)	ppb
toluene	3500	ppb
xylene (total)	1060	ppb

(J = estimated value)

In October of 1990 approximately 20 more cubic yards of soil was excavated in the drum area. As excavation continued, air monitoring readings continued to rise, indicating further contamination. To determine the vertical and horizontal extent of contamination, test-pits were excavated and four monitor wells were installed. Samples collected at this time revealed that the remaining soil was still contaminated and one groundwater sample showed the presence of benzene at 55 parts per billion (ppb).

Currently, the U.S. Environmental Protection Agency, together with the Illinois Environmental Protection Agency, is reviewing a work plan submitted by Prairie Environmental Specialists to undertake further remedial action at the site. According to Tom Mangan, President of Prairie Environmental Specialists, the proposed plan calls for a soil vapor extraction system and a groundwater pump-and-treat system to be installed at the site.

On July 23, 1991, Judy Triller and Kim Nika of the Illinois Environmental Protection Agency conducted a site reconnaissance of the Drum Disposal Area. At this time the site was found to be vacant and easily accessible as it was not enclosed by a fence. Most of the site was found to consist of open area covered with gravel and sparse

vegetation. The borders of the site contained more brush, trees, and grass. Several large rusty tanks and various pieces of equipment were noted in the northwestern part of the site. Also in this part of the site was the former drum area and area of excavated soil. This area was surrounded by a fallen snow fence and several monitor wells. Concrete blocks and a cable prevented vehicles from entering the site from Southwest Highway.

Information obtained from area well logs and the Illinois
State Geological Survey publication, Groundwater

Possibilities in Northeastern Illinois, indicates that the geology of the area consists of alternating layers of sand/gravel and clay to depths ranging from 125 feet to over 200 feet. Underlying these glacial deposits are bedrock formations of dolomite, shale and sandstone. At the site itself, surface material consists of fill material composed of demolition and construction debris. According to U.S.

Environmental Protection Agency records, during soil excavation at the site groundwater was encountered at approximately 12 feet.

The dolomite aquifer is the main source of drinking water in the vicinity of the site. According to Illinois Environmental Protection Agency Division of Public Water Supplies' facility inventory there are five public wells located within four miles of the site. Two of the wells are located approximately

2.6 miles from the site and supply water to the village of Mokena. These wells draw water from the dolomite aquifer at depths from 90 feet to 420 feet and serve a population of approximately 5000.

The Metro Utility Company - Chickasaw Hills Division owns a well located approximately 2.7 miles northwest of the site. According to Robert Linenberger, General Manager of Metro Utility Co., this well (known as well 3) is one of a system of four wells that serves unincorporated areas of eastern Homer Township. This well draws water from the dolomite aquifer at depths of 155 feet to 300 feet. The four-well system serves approximately 8250 people.

The other two wells located within four miles of the site are owned by Citizens Utility. These wells are known as well 1 and well 2 and are located approximately 3.5 miles southeast of the site. According to Marvin Strong, Operations Manager for Citizens Utility, they serve the unincorporated area known as Arbury Hills and the industrial park of the Village of Mokena. Both wells draw water from the dolomite aquifer - well 1 draws water from depths of 121 feet to 457 feet while well 2 draws water from depths of 117 feet to 435 feet.

Others residing within four miles of the site obtain drinking water form Lake Michigan, from wells located more than four miles from the site, or from private wells. Well logs from

the area indicate that the majority of private wells in the area draw water from the dolomite aquifer. It is estimated that approximately 14,300 people obtain water from sources located within four miles of the site.

Surface water runoff from the site enters Marley Creek, which is located northeast and east of the site. Marley Creek flows southwest for approximately 4.5 miles at which point it converges with Hickory Creek. The surface water route continues along Hickory Creek, flowing east and south for approximately 10 miles where it enters the Des Plaines River (at Joliet). The remainder of the surface water route continues along the Des Plaines River for approximately 0.5 miles. There are no known surface water drinking water intakes within 15 miles downstream of the site. According to U.S. Fish and Wildlife Service National Wetlands Inventory maps, a small wetland area is located on the Prairie Material Sales property northeast of the actual drum area. This area may be located in the overland runoff route. Approximately 3.75 miles of wetland frontage exist along Marley Creek (flow estimated to be approximately 10 cubic feet per second) downstream of the site. Information obtained from the Illinois Department of Conservation indicates that Hickory Creek is considered a moderate fishery resource.

No on-going air emission problems are known to exist at the site. However, as state previously, air monitoring readings

rose above background during excavation of soil from the drum area. Furthermore, the National Wetlands Inventory map shows approximately 30 acres of wetlands within 0.5 miles of the site.

The presence of contaminated soil at the site leads to the possibility of a direct contact hazard. The site is easily accessible and although the area is not heavily populated, a residential area is located just northwest of the site. As stated earlier, concrete blocks and a cable prevent vehicles from entering the site.

Based on information known about the facility and surrounding area at this time, two primary targets associated with the surface water path have been identified - Marley Creek and wetlands associated with the overland runoff route. Other concerns at the site include the presence of contaminants in shallow groundwater and the potential for direct contact with contaminated soil. Also to be considered is the fact that remedial work has been carried out at the site and currently plans for additional remedial work are underway.

Due to these factors a low priority status has been assigned to the Drum Disposal Area site. It is recommended that the Region V Offices of the U.S. Environmental Protection Agency advance this site to the Screening Site Inspection stage of the CERCLA Pre-Remedial process.

BIBLIOGRAPHY

Bergstrom, R.E.; Foster, J.W.; Selkregg, Lidia F.; and Pryor, W.A. <u>Groundwater Possibilities in Northeastern Illinois</u>, 1955.

Buchler, Bob. Water Operator, Village of Mokena. September 10, 1991 telephone interview.

Hack, Larry. Water Operator, Village of Orland Park. September 25, 1991 telephone interview.

Illinois Department of Conservation, Impact Analysis Section, Division of Planning. August 8, 1991 letter.

Illinois Environmental Protection Agency, Division of Land Pollution Control files for Prairie Material Sales.

Illinois Environmental Protection Agency, Division of Public Water Supplies. Facility Inventory.

Illinois State Water Survey. Well logs from the area.

Mangan, Tom. President, Prairie Environmental Specialists. September 18, 1991 telephone interview.

Strong, Marvin. Operations Manager, Citizens Utility. September 17, 1991 telephone interview.

U.S. Environmental Protection Agency, Emergency Response Section files for Southwest Highway Drums.

Zentak, Leonard. U.S.EPA. September 26, 1991 telephone interview.

SECTION 2 EPA FORM 2070-12

"Potential Hazardous Waste Site Preliminary Assessment"

\$EPA	PART 1 - STIE INFORMATION AND ASSESSMENT			_	LIDENTIFIC OI STATE OF	
II. SITE NAME AND LOCATION	•					
Drum Disposal	Area*		th St or Specific Construction			Hwy.
Orland Park	LONGITUDE	IL	6046Z (COOK	- /	or continue cond continue cond cond cond cond cond cond cond cond
413351	0815400				·	
In Orland Park the northeast cor	follow Rt. 10 wi ner of Route	est/s 6 and	south. Th	site Street	is loc	cated at
IIL RESPONSIBLE PARTIES	·		_			
Prairie Material	Soles Inc.		Ol Wes		h Si	trect
Bridgeview or OPERATOR IS WAS AND STATE OF THE			60455			
Some As Above	•	10 STATE	11 2P COOE	12 TELEPHONE	MANGER	
1 .		1	}	()	!	
IS TYPE OF OWNERSHIP (CHARLES) A. PRIVATE B. FEDERA F. OTHER:	(Agency name) (Security)		C C. STATE	CID.COUNTY	CI E. MUI	NICPAL.
C A. RCRA 3001 DATE RECEIVED: MOR	IN DAY YEAR I B. UNCONTRO	KLED WAST	E SITE (CERCLA 144 a)	DATE RECEIV	ED: HONTH O	AV YEAR B C NONE
IV. CHARACTERIZATION OF POTENTA	BY (Cheer of the capter)				·	
SYES DATE 5 / 189		FFICIAL	ACTOR (I.C. II F. OTHER:		CI D. OTHER	CONTRACTOR
02 SITE STATUS (Change area)	03 YEARS OF OF					
DI AL ACTIVE & B. INACTIVE DI C.	UNICHOWN	\$£000000	EMP EMERGINE		E UNKNOW	•
Solvents - Meth toluene, xylene	ylene Chloride	, Acc	tone, 2.	- butan	one	
Soil Contaminati Groundwater Cor Surface Water Co	on itamination					
V. PRIORITY ASSESSMENT	3.1,3,1.1.14,1011					·
01 PRIORITY FOR INSPECTION (CHEST SHE FRANCE) CI A. HIGH CI 8. I	EDIUM E C. LOW	returnation and f	O. NONE	Carrettens and I		
VL INFORMATION AVAILABLE FROM						
01 CONTACT	OZ OF (Agency)On	-	 			03 TELEPHONE NUMBER
Tom Mangan 104 PERSON RESPONSIBLE FOR ASSESSMENT	Projecie OS MOZENCO	Env	ron. Sc	OCCIO/	STS	1708) 293 - 444.
LJudy J. Triller		DL		1	2-6760	1 6 27 01

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION

I. IDENTIFICATION

OI STATE OF SITE NUMBER

IL D984791681

A SOUD A POWDER FF C SLUDGE D OTHER RIL WASTE TYPE CATEGORY SULU OLW SOL PSD OCC FOC ACD BAS MES IV. HAZARDOUS	G GAS	TONS CUBIC YARDS NO OF DRUMS	Unknown	OJ WASTE CHARACTE A TOXIC B CORROS C RADIOAL D PERSIST	E SOLUBL SIVE F INFECTI STIVE G FLAMM	LE I HIGHLY V NOUS J EXPLOSI ABLE K REACTIV	ME VE NATIBLE
B POWDER FF C SLUDGE D OTHER D OTHER BIL WASTE TYPE CATEGORY SUL OLW SOL PSD OCC NCC ACD BAS MES IV. HAZARDOUS	SUBSTANCE N	TONS CUBIC YARDS NO OF DRUMS		B CORROS C RADIOAG	TIVE F INFECTI STIVE G FLAMM	IOUS JEXPLOSI IABLE K REACTIV BLE L INCOMP	IVE /E ATIBLE
CATEGORY SLU OLW SOL PSO OCC NOC ACD BAS MES IV. HAZARDOUS OI CATEGORY	SUBSTANCE N SLUDGE CILY WASTE	NO OF DRUMS	Uuknown	O PERSIST	ent 📳 H igmitae		
CATEGORY SLU OLW SOL PSO OCC OCC ACD BAS MES IV. HAZARDOUS	SUBSTANCE N SLUDGE CILY WASTE	NO OF DRUMS	Uliviion	<u> </u>		m (10) A-1	
CATEGORY SLU OLW SOL PSD OCC FOC ACD BAS MES IV. HAZARDOUS	SUBSTANCE N SLUDGE ORY WASTE	1AME	•				
SLU OLW SOL PSD OCC FOC FOC ACD BAS MES IV. HAZARDOUS	SLUDGE OILY WASTE	TAME					
OLW SOL PSD OCC OCC OCC ACD BAS MES IV. HAZARDOUS	OLY WASTE		01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS		
SOL PSO OCC OCC OC ACD BAS MES IV. HAZARDOUS							
PSD OCC NOC ACD BAS MES IV. HAZARDOUS	SOLVENTS			·			
OCC OC ACD BAS MES IV. HAZARDOUS	-		Mokoowa				
ACD BAS MES IV. HAZARDOUS	PESTICIDES						
ACD BAS MES IV. HAZARDOUS	OTHER ORGANIC C	HEMICALS					
BAS MES IV. HAZARDOUS	INORGANIC CHEMIC	CALS					
MES IV. HAZARDOUS DI CATEGORY	ACI CS			T			
IV. HAZARDOUS	BASES						
O1 CATEGORY	HEAVY METALS						
	S SUBSTANCES	-	nery calou CAS Humanes		i 	**************************************	
SOL	02 SUBSTANCE	NAME	03 CAS NUMBER	04 STORAGE DIS	POSAL METHOD	05 CONCENTRATION	OS MEASURE OF
501							
	Acetone			Fd. in so	1 samples	4010	pph
501	2 - butano	one		1/		2/02 (J)	Pp b
SOL	Methylene (,,		462	-pph-
SOL	Toluène			li li		3500	COD
SOL	Xylene			"		1060	oob
							1
				T			
							T
							1
							I
							1
							
V FFFDSTOCY	KS 1500 Aggreen to CAS More					<u> </u>	<u> </u>
CATEGORY	O1 FEEDSTO		02 CAS MUMBER	CATEGORY	01 FEEDSTOCK NAME 02 CAS		02 CAS MUMBER
FDS				FOS			
FDS						1	
FOS		· <u>·</u>		FDS			
FCS				FOS FOS			·

IEPA Division of Land Pollution Control Files (Prairie Material Sales) U.S. EPA Emergency Response Section Files (Southwest Hwy. Drums)

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

L IDENTIFICATION

101 STATE 07 SITE MANER

TL D984791/681

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS IL HAZAROOUS CONDITIONS AND INCIDENTS


7/) 7/0	02 2 OBSERVED IDATE) POTENTIAL ALLEGED 04 NARRATIVE DESCRIPTION
The presence of contamir	nonts in on-site soil, together with the the possibility of groundwater contam- compled showed benzene at approx. 50ppb.
The presence of contaminal	oziosservedidate I RPOTENTIAL :: ALEGED on HARRATIVE DESCRIPTION on - site soil, tagether with the leads to the possibility of surface ey Creek.
	02 C OBSERVED (DATE) POTENTIAL C ALLEGED 04 MARRATIVE DESCRIPTION
None Known	
In the fall of 1989 samples ve found to be ignitable. The but soil at the site is still	oz cosserved idate
The prescince of contami the possibility of a direct	nated soil at the site leads .to et contact hazard.
Soil samples at the site solvents.	OR & OBSERVEDIDATE 6-17-89 1 POTENTIAL ALLEGED OF MARKATIVE DESCRIPTION WE'RE FOUND to CONTAIN VARIOUS
of the dranking water contamnation 14300. Traces of benzene were detected Some nearby redidents util	ozilosservedidate i motental alleged of harrative description ted in ground water (shallow) at the site. ize groundwater for drinking.
01 B H. WORKER EXPOSURE INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 (1 OBSERVED (DATE
. None Known - Site	currently inactive
01 JI POPULATION EXPOSURE PLUMY 03 POPULATION POTENTIALLY AFFECTED	02 (1 OBSERVED (DATE


POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

L DENTIFICATION
OI STATE OF SITE MANUEL
TL D98479/68/


E HAZARDOUS CONDITIONS AND INCIDENTS (Comme		
01 III J. DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:) S POTENTIAL (] ALLEGED
Wetlands are located no	rthwest of former	drum area.
Contaminants in the soil co	ould possibly be car	ried to this area
by surface runoff.	•	
01 E K. DAMAGE TO FALMA	02 (] OBSERVED (DATE:	B POTENTIAL CI ALLEGED
See "J" above. Also, if cor	staminants i are an	- d l- nearhy
surface water, aquatic life	of the stranger	They for med by
Sur reserve raquar re mile	or the stream dout	a be unecres.
01 III L. CONTAMINATION OF FOCO CHAIN 04 NARRATIVE DESCRIPTION	02 (1) OBSERVED (DATE:) @ POTENTIAL . CI ALLEGED
See "K" above		
01 BM UNSTABLE CONTAINMENT OF WASTES	02 E OBSERVED (DATE: 1989) [] POTENTAL [] ALLEGED .
03 POPULATION POTENTIALLY AFFECTED.	04 NARRATIVE DESCRIPTION	
Leaking drums at the sit	e resulted in Soil	contamination.
01; N DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 () OBSERVED (DATE:	.) POTENTIAL ALLEGED
None Known		
World Milett	•	•
01 C. O. CONTAMNATION OF SEWERS, STORM DRAINS, WATE 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:	.) D POTENTIAL D ALLEGED
None Known.		·
None hown.		
01 ELP ELEGALANAUTHORIZED DUMPING		
04 NARRATIVE DESCRIPTION	02 S OBSERVED (DATE:	
The site is a vocant lot	in a rural area wh	here unquthorized
dumping was known to be	e a problem.	
OF DESCRIPTION OF THE DESCRIPTION OF THE OWNER OWNE		
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALL	EURED HAZARUS	
		•
		·
IL TOTAL POPULATION POTENTIALLY AFFECTED: /4	/300	
IV. COMMENTS		
	e was laft by an	walland andy
Leaking drums at the site	moved + some poots	minated sail has been
exposited Dian in further		in the second second
excavated. Plans for further r	cincolation activiti	es are unacrway.
	M. surem energies, reposite	
IEPA Division of Land Poll	ution Control tiles (Prairie Material Sales)
U.S. EPA Emergency Respon	ruse Section files (S	Bouthwest Hwy Drums)

SECTION 3 MAPS






Base Map: DEPARTMENT OF TRANSPORTATION
OFFICE OF PLANNING AND PROGRAMMING



Base Map: Weston Major Programs Division, 10-24-90.

DRUM DISPOSAL AREA Site Map



Base Map: USGS 7.5 Minute, 1963 Mokena Quadrangle; photorevised 1973.

SECTION 4 PHOTOGRAPHS




DRUM DISPOSAL AREA Orland Park, Cook Co. Illinois



1988 Aerial Photo provided by Illinois Dept. of Transportation.

DRUM DISPOSAL AREA
Orland Park, Cook Co. Illinois



DRUM DISPOSAL AREA
PHOTOGRAPH LOCATION MAP

DATE: JULY 23, 1991

TIME: 10:15 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

PHOTO NUMBER: 1

LOCATION: ILD984791681
DRUM DISPOSAL AREA

EMPTY TANK ON-SITE
NEAR DRUM AREA.



DATE: JULY 23, 1991

TIME: 10:20 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

PHOTO NUMBER _____2

LOCATION: ILD984791681
DRUM DISPOSAL AREA

REMNANT OF DRUM

ON-SITE.



DATE: JULY 23, 1991

TIME: 10:20 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

PHOTO NUMBER 3

LOCATION: ILD984791681
DRUM DISPOSAL AREA

EMPTY TANKS AND
EQUIPMENT ON-SITE.



TIME: 10:25 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

DATE: JULY 23, 1991

PHOTO NUMBER ___4

LOCATION: <u>ILD984791681</u>
DRUM DISPOSAL AREA

EMPTY RUSTED DRUMS
AND MONITOR WELL



DATE: JULY 23, 1991

TIME: 10:25 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

PHOTO NUMBER 5

LOCATION: ILD984791681
DRUM DISPOSAL AREA

RUSTED DRUM ON-SITE



DATE: JULY 23, 1991

TIME: 10:30 AM

PHOTOGRAPH TAKEN BY: KIM NIKA

PHOTO NUMBER 6

LOCATION: <u>ILD 984791681</u> DRUM DISPOSAL AREA

FORMER LOCATION OF DRUMS
AND AREA OF EXCAVATED
SOIL.



DATE: JULY 23, 1991

TIME: 10:30 AM

PHOTOGRAPH TAKEN BY:
KIM NIKA

PHOTO NUMBER 7

LOCATION: ILD984791681
DRUM DISPOSAL AREA

AREA OF EXCAVATED SOIL.



DATE: <u>JULY 23, 1991</u>

TIME: 10:35 AM

PHOTOGRAPH TAKEN BY:

KIM NIKA

PHOTO NUMBER 8

LOCATION: <u>ILD984791681</u>
DRUM DISPOSAL AREA

RUSTED TANKS AND EQUIPMENT.



DATE: JULY 23, 1991

TIME: 10:40 AM

PHOTOGRAPH TAKEN BY:

KIM NIKA

PHOTO NUMBER 9

LOCATION: <u>ILD984791681</u>
DRUM DISPOSAL AREA

VIEW FROM SOUTHWEST
HIGHWAY. CONCRETE BLOCKS
AND CABLE BLOCKING
ENTRANCE ONTO SITE.



DATE: <u>JULY 23, 1991</u>

TIME: 10:45 AM

PHOTOGRAPH TAKEN BY:

KIM NIKA

PHOTO NUMBER _____10

LOCATION: <u>ILD984791681</u>

DRUM DISPOSAL AREA


AREA NEAR ACCESS ROAD



SECTION 5 SUPPORTING DOCUMENTATION AND REFERENCES

REFERENCES

- 1. November 7, 1990 letter from Roy F. Weston, Inc. to U.S.EPA with information concerning southwest highway Drum site.
- 2. September 10, 1991 Telephone conversation Record with Bob Buchler, Water Operator, Village of Mokena.
- 3. Septhember 17, 1991 Telephone Conversation Record with Marvin Strong, Operations Manager, Citizens Utility.
- 4. September 18, 1991 Telephone conversation Record with Tom Mangan, President, Prairie Environmental Specialists.
- 5. September 25, 1991 Telephone conversation Record with Larry hack, Water operator, Orland Park.
- 6. September 26, 1991 telephone conversation Record with Leonard Zentak of U.S.EPA.
- 7. Excerpt from Illinois State Geological Survey publication, <u>Groundwater Possibilities in Northeastern Illinois</u>, 1955.
- 8. Well logs from the area obtained through Illinois State Water Survey.





River Center, 144 North Canal Street, 5th Floor, Suite 855, 5th Chicago, H. 50606 • (312) 993-1067 • FAN, 342, 993-0226.

TECHNICAL ASSISTANCE TEAM FOR FMERGENCY RESPONSE REMOVAL AND PREVENTION EPA CONTRACT 68-01-7367

Mr. Duane Heaton Deputy Project Officer Emergency Response Section, 5HS - 12 U.S. Environmental Protection Agency 230 South Dearborn Street Chicago, Illinois 60604 November 7, 1990

TAT-05-G2-02258

Re: Southwest Highway, Orland Park, Illinois TDD# 5-9010-03

Dear Mr. Heaton:

On August 8, 1989, the U.S. Environmental Protection Agency, (U.S. EPA) tasked the Technical Assistance Team (TAT) to monitor the potentially responsible party (PRP) removal action at the Southwest Highway Drum/Prairie Materials (SW Highway) site in Orland Park, Cook County, Illinois (Figure 1). The five-acre site, which is owned by Prairie Materials, (a concrete foundry company), consists of construction and demolition fill, and contained, prior to the start of the PRP removal action, several large, empty concrete batch tanks and a number of drums. The site is bordered by a wetland to the northeast, the Norfolk and Western Railroad to the east, 179th Street to the south, and Southwest Highway (Route 6) to the west (Figure 2).

Prompted by a resident compliant of illegal dumping and filling of wetlands, the U.S. EPA and TAT performed a site assessment (TDD# 5-8905-23) on May 30, 1989. TAT observed five empty 10,000- to 15,000-gallon tanks, four empty 500- to 1,000-gallon tanks, and approximately 42 rusted 55-gallon drums, some of which indicated signs of previous leakage. TAT collected samples from five of the drums and from an area of stained soil. Results of analyses performed on the samples indicated Resource Conservation and Recovery Act (RCRA) ignitability characteristics in the drummed material and solvent contamination in the soil. To alleviate the on-site hazards, the U.S. EPA requested the PRP fund a removal-action.

PRP removal efforts began on June 17, 1989, when snow fencing and signs were installed around the drum area. On August 9, 1989, representatives from ATEC Associates, Inc. (ATEC) were mobilized to the site to conduct drum and soil sampling for disposal acceptance. One composite soil and 38 drum samples were collected and analyzed by ATEC.

Roy F. Weston, Inc.
MAJOR PROGRAMS DIVISION
In Association with ICE Technology



on November 21, 1989, ATEC resampled some of the drums sampled on August 9, 1989 because their identification numbers washed off. Additionally, half-buried drums were excavated and sampled. On November 23, 1989, 24 drums were overpacked by SET Environmental, Inc. (SET) personnel.

-4-

on December 6, 1989, Metropolitan Waste Systems, Inc. (MWS) excavated approximately one foot of soil from an area approximately 20 feet by 20 feet and placed the soil into a 20-cubic yard rolloff. At this time, ATEC collected a composite sample of the soil in the rolloff, and split the sample with the TAT for selected volatile organics analysis. TAT samples were analyzed at Grace Analytical Laboratory, Inc., in Berkeley, Illinois under TAT Analytical Services TDD# 5-8912-L04. Results of this sampling are shown below.

TABLE 1

Summary of TAT Analytical Results for Selected Volatile Organics in Soil

SW Highway Site, Orland Park, Illinois December 6, 1989

	======
Contaminant in	n ppb ¦
======================================	======
Methylene Chloride	462
Acetone	4010
2-Butanone	262J
Toluene	3500
Xylene (total)	1060

J = estimated value

On December 12, 1989, SET personnel transported 15 drums of ignitable material and one drum of caustic to Treatment #1 in Houston, Texas, and 17 drums of non-ignitable material to Ultra Chem in Joliet, Illinois. On May 10, 1990, ATEC personnel resampled the soil in the rolloff box, split the sample with the TAT and analyzed the samples for Toxicity Characteristic Leaching Procedure (TCLP)-solvents analysis. TAT samples were analyzed at Weston-Gulf Coast Laboratories, Inc., in University Park, Illinois, under TAT Analytical Services TDD# 5-9005-L05. Results of this sampling are presented below.



Mr. Duane Heaton

TABLE 2


Summary of TAT Analytical Results for TCLP solvents in soil

SW Highway site, Orland Park, Illinois May 10, 1990

Contaminant	in ppb
Vinyl chloride 1,1-Dichloroethene Chloroform 1,2-Dichloroethane Carbon Tetrachloride 2-Butanone Trichloroethene Benzene Tetrachloroethene Chlorobenzene	BDL BDL BDL BDL BDL BDL 2 J BDL 4 J

In September 1990, MWS received an Illinois Environmental Protection Agency (IEPA) permit to dispose of excavated soil from the drum area. In October 1990, representatives from the PRP, Prairie Materials, and Chemical Waste Management (CWM) signed a contract for acceptance of the excavated soil at the CWM CID Landfill in Chicago, Illinois. MWS then planned to remobilize to excavate an additional two to three feet of soil.

On October 19, 1990, MWS excavated approximately 20 cubic yards of soil into a dump truck. The dump truck transported the soil to CID Landfill. As the excavation proceeded and air monitoring readings via HNU photoionization detector (HNU) continued to rise, it was evident that the contaminated area was larger than projected. In an attempt to determine the horizontal and vertical extent of contamination, three six-foot deep test pits were excavated in the middle of the drum area (Figure 3). The excavation within the drum area stopped at 12 feet because water (either ground water or a buried stream bed) was encountered. HNU readings in pits 1 and 2 were between one and two units, while HNU readings in pit 3 were



Mr. Duane Heaton

-7-

November 7, 1990

between five and ten units. Background levels were approximately 0.1 units. HNU readings in pit 4 were between 100 and 400 units.

On October 22, 1990, the 20-cubic yard rolloff that has been on site since December 1989 was transported to the CID Landfill for disposal.

On October 29 and 30, 1990, TAT and PRP contractor Prairie Environmental Specialists of West Chicago returned to the site. Prairie Environmental installed four monitoring wells and drilled nine soil borings (Figure 4). Split spoon samples were collected from the soil borings at 3.5 to 5 feet, 8.5 to 10 feet, 10 to 12 feet, and 12 to 14 feet. Prairie Environmental is currently analyzing these samples at an EPA-approved laboratory.

Should you have any questions or require additional information, please feel free to contact us.

Very Truly Yours,

William R. Doyle


Technical Assistance Team

Leader, Region V

MB:ap


cc:Len Zintak, OSC

attachment




COUNTY	DIPC
Drum Disposal Area 1 ILD 98	24791681. I. D. or FILE NO.
Re: Village of Mokena wells	
Conversation with: Bob Buchler	Water Operator
(\(\sum \) I Called Party () Party Called	•
() Complainant () Violator () F	,
What I Said:	What Other Party Said:
O Introduction . I'd	
Like to get some information	1
about the rallage wells.	
How many wells do you	
traine?	2 yele train 3 wello.
and the second s	
3) One they all themsed?	@ Well their in 3 rifl.
	locations + they no all primy
	into the distribution ouster
Does any me well produce	
more than 40% of the total?	@ Do tile potate strem on
	a duly enois so they all
	produce alout, 33%.
Tistat about this well- I think	
it's mo. 4 - mean a periorge	
apposed plant? To it In	
indistrial use?	11/ein rapped 2 millo
	One is just west of
	use reverse side if necessary
$ \begin{array}{c c} \hline & J_{1} & J_{2} & J_{3} \\ \hline & J_{3} & J_{3} & J_{3} \\ \hline & J$	<u>FPS T</u> Title
EPA 129 (Rev. 1/81)	11616

COOK	DLPC		
COMIT	DIVISION		
Drum Disposal Area / ILD 984791681. I. D. or FILE NO Re: Village of Makena wells / water supply Conversation with: Bob Buchter, Water Operator			
		() I Called Party () Party Ca	lled Me DATE 9 1/0/9/ TIME / :30
		() Complainant () Violator () Public Inquiry () Partitioner	
What I Said:	What Other Party Said:		
	® 708-628-2626		
·	O guy marmed Steers		
, and the second se	Prillippi.		
Thanks. Opprox. how			
the second secon			
many people do your.	Ø 01 - 1 5000		
LIKUD DINLR .	@ Olmub 5000.		
Thronks for the inform-			
otion.			
Service Service Control of the Contr	A COMPANY OF THE STATE OF THE S		
. galante :	Company of the Compan		
e de la companya del companya de la companya de la companya del companya de la co			
	use reverse side if necessar		
$\bigcap_{i=1}^{n} A_{i} = \bigcap_{i=1}^{n} A_{i} = \bigcap_{i$	FPS I		
L 532-0727 Signature	Title		




_ Look	\underline{DLPC}
COUNTY	DIVISION
Drum Disposal Area 1 ILD 9	8479/68/. I. D. or FILE NO
Re: Citizens Utility Water Dist	•
·	
Conversation with: Marvin Strong, C	
() I Called Party () Party Called	d Me DATE 9 1/71 91 TIME 9:15 A
() Complainant () Violator ()	Public Inquiry () Partitioner
What I Said:	What Other Party Said:
1 Introduction. I'm trum	9
to figure outs water pupply	
in onea posithwestry Onlan	
Park.	DROY, MRIK got, Il Mot
A trial partition of the contract of the contr	apotemoi in Chicago pulhi
and the same of th	
	nea from Mr. Prospect
	month to Mokema- Frankly
	in pouth. Two of the pyption
	are on lake waters may
والمنظور ومنهما المراجع المناهمين المناهمين المناهمين المناهمين المناهمين والمناهمين المناهمين المناهمين المناهمين	
	i lutine:
	Tile hove. 2 Orlany Hills
	unella (1+2). Then there's
	another well -5 miles no
	in Anland Hills that's
	strictly stomothy.
3 The 2 OrlHING HILLO WELLOW-	
do they peaks likely that	•
	use reverse side if necessary
Churcy J. Triller	EPS I
IL 532-0727 EPA 129 (Rev. 1/81) Signature	Title

Conversation wi	•	ng, Operations Mgr.
(/) I Called P	Party () Party C	alled Me DATE <u>9 1/719/</u> TIME <u>9 :</u> () Public Inquiry () Partitioner
Wh	at I Said:	What Other Party Said:
	,	ito Soke unter, une.
		_ Luis from Timber Pork
		There is a well, trut,
		off-lime.
South mo	ti sien conni	ectid!
		$\frac{1}{\sqrt{10717}}$
TUTILLE IN.	this ones do	
JAMI DENIA.		Dylle perine, Empirale
		The state of the s
		from 159 th St to 96
- market services and services are services and services are services are services are services are services		Manheim to wate, 17
		At. to posith a 88th Oir
0		the conti.
Marit Co	on anuthing	4.1.4.2
1) 1/C/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	RODOLL TUND TU	B.O. t. M. A. think
		- The peally, I mink I
	e par e augumente des de la presión de presión de la p	printely oumed typa



COOK	DLPC
	DIVISION
Drum Disposal Area / ILD 98	
Re: Records concerning Drum. Disp	asal Area
Conversation with: Tom Mangan, P	resident of Provine Specialists
() I Called Party () Party Called	
() Complainant () Violator () F	Public Inquiry (-) Partitioner
What I Said:	What Other Party Said:
Introduction. Have records	
up to Oct. of 1990 when mon-	
itoring untle were unstabled	
+ more soil samples taken +	-
om trying to find out what	- August Alice de
troppemed often that.	Tyle hove a reportion
0	hudrogeologic findings +
	dont for remedial action
	_umk.plam.
Market Control of the	The area is actually less
	than one acre. The drum
	MAN IN a stallow departs
-TIMAD MIN the pamples offer!	
	1 One of the wells had
	tengene at 55 ppb. The rest
and the second of the second community of the second of th	were clean. The gra.
and the second s	moter flouris south -
the contraction of the contract of the contrac	
	use reverse side if necessary
11,532,0727 Signature	FPS I' Title
EPA 129 (Rev. 1/81)	litle .

	Cook	DLPC
	COUNT	DIVISION
	Drum Diaposal Area / ILD 98	479/68/ . I. D. or FILE NO
	e: Records concerning Drum Disposal Area	
•	Conversation with: Tom Mangan, F	•
	(/) I Called Party () Party Called	
	() Complainant () Violator ()	•
	What I Said:	What Other Party Said:
	,	urbere we're working.
		don't think ib would
		unteres Art. they Bow. to
6	Do now know if city worten	
	goes, that for pouth?	@ Dr. J. don't, Trelieix. it.
		Mass. The homesum the
	The second secon	and true apot wellow
		from the well logo we're
		stallantensock. Benon
		I think in almit 90 feets
		+ there are some clay
		enyens in the upper
		layera
U	Could a get a copy of some	
	of the nicordo/nepultor:	use reverse side if necessary
	Judy Jailier	ERS I
	IL 532-0727 EPA 129 (Rev. 1/81) Signature	Title




Cook	DLPG
	34791681 DIVISION
Drum Disposal Area / ILD #	7 . I. D. or FILE NO
Re: Oclam Park Water Supply +	Distribution
Conversation with: Locry Hock, W	nter Operator
() I Called Party () Party Called	
() Complainant () Violator () P	•
What I Said:	What Other Party Said:
1 Introduction	
Telould like to get an idea	
about the motor supply +	
antilution of Orland Park.	
Does the rallage house wells, as	L Angele Andrews
ore you on dake unter!?	1 716 out notes Inom
	Churage Jake Michigan.
3 Doen troop take come of sume the	
entire rullage, on one there.	
some places in corp. Loumdonie	
shot non't, get, city unter?	
	ON DENING THE TRUPPED
- Jude sporting and the second and t	+ some priori outside the
en e	TRILAGE get TRILAGE MATER).
3) 1 2000 1 100 100 100 100 100 100 100 10	theritize Gove thereings thereing
5) I know there are some men	
Murelopments along South -	
west theref - mean 179th St	use reverse side if necessary
Chay a. Trille	EPS
IL 532-0727 Signature	Title

COUNTY	DIVISION	
DRUM DISPOSAL AREA / TID 98479/68/ I. D. OF FILE NO		
() I Called Party () Party Calle () Complainant () Violator (ed Me DATE <u>9 12579/</u> TIME <u>4:00,</u>) Public Inquiry () Partitioner	
What I Said:	What Other Party Said:	
	family tromes, lad ma	
	<u> </u>	
. <u> </u>	There's Olpine Subdunsio	
	that doesn't have Till	
	Motor He pution willer.	
tisteria that pulminaion.	>	
	@ str. nt 1107th + Tild & Rd	
The second secon	Donth of 167th anot of 1/64	
egy (please the shape of the sh	Rood.	
The second secon	7.	
	The state of the s	
	The second secon	
and the second of the second o	 *	
•	use reverse side if necessary	
Quay Q. Trille	FRSI	
IL 532-0727 EPA 129 (Rev. 1/81) Signature	Title	



٠.	COOK	DLPC
		OLVISIUN
	DRUM DISPOSAL AREA / ILD 9	
	Re: General Information about Si	
	Conversation with: Leonard Zentok	
	() I Called Party () Party Called () Complainant () Violator ()	•
	What I Said:	What Other Party Said:
0	Introduction. I trace of few	
	questions about the Southwest	
	HUND DOUMA DITE. TITTERE NO	
	thimps stand night mous?	1 They're remared the drum
		they're permared the
		contominated pail to
		approx. 12 feet. But there's
		oull contaminated pail +
		the and water appears to
		1x impacted Tilhen they
		dug the pit there was
		unter + il pada pheem.
3	logod. unter at 12 feet?	
		1 around there - depende
		m the naim.
		They're proposed a poil
	Angular of the state of the sta	zoom entraction austern +
	and the second of the second o	a anaumdumtu, nump w use reverse side if necessary
		use reverse side if necessary
	IL 532-6727 EPA 129 (Rev. 1/81) Signature	<u>EPS. I</u> Title

COOK	DIPC
_ ,	10 984791681 I. D. or FILE NO
Re: General Information ab	
Conversation with: Leonard 7	
(I Called Party () Party Ca	alled Me DATE <u>9 126191</u> TIME <u>10:15 a.</u> () Public Inquiry () Partitioner
What I Said:	What Other Party Said:
Do you know amustring o	
the geology at the pite?	1 eta fill eta trem filler
	with construction delnis
	no there a inserting
The second secon	motorials - some gonie
	<u>Clou</u>
Hore then them amy nample	00
or will there for at other pe	2010
of the site - or frist asour	and product a transportation of the second
the daym area?	It's from anound the
	druma, tile don't really
	trained reprom to suspect
	noil way do addition
	poil pampling - and we ma
The second secon	somple those private sull
though you promple the up	rllo
	use reverse side if necessary
HERRY C. SIGNATURE	<u>ERS I</u>



STATE OF ILLINOIS
WILLIAM G. STRATTON, Governor
DEPARTMENT OF REGISTRATION AND EDUCATION
VERA M. BINKS, Director

STATE GEOLOGICAL SURVEY
JOHN C. FRYE, Chief
URBANA

CIRCULAR 198

GROUNDWATER POSSIBILITIES IN NORTHEASTERN ILLINOIS

A Preliminary Geologic Report

BY

R. E. BERGSTROM, J. W. FOSTER, LIDIA F. SELKREGG, and W. A. PRYOR

Service activities concerning groundwater are performed jointly by the Illinois State Geological Survey and the Illinois State Water Survey

LIBRARY

RICHARD ROTECTION AGENC

STATE OF ILLINOIS

SPRINGFIELD, ILLINOIS

PRINTED BY AUTHORITY OF THE STATE OF ILLINOIS

URBANA, ILLINOIS
1 9 5 5

GROUNDWATER POSSIBILITIES IN NORTHEASTERN ILLINOIS

A Preliminary Geologic Report

Вy

Robert E. Bergstrom, John W. Foster, Lidia F. Selkregg and Wayne A. Pryor

ABSTRACT

Groundwater possibilities for domestic, municipal, and industrial supplies in northeastern Illinois range from poor to excellent. This report summarizes the geologic conditions controlling the availability of groundwater and suggests ways to obtain it under the prevailing conditions. Maps are presented which show: 1) groundwater possibilities from sand and gravel deposits, 2) groundwater possibilities in shallow bedrock, and 3) depth to the Galesville sandstone, the principal water-yielding formation for industrial and municipal groundwater in northeastern Illinois.

INTRODUCTION

Water that occurs in the earth and that is tapped with varying success by farm, municipal, and industrial wells is one of our most valuable natural resources. In some areas it is readily available for all purposes - from small domestic supplies to great industrial or municipal supplies - whereas in other areas even a little groundwater is difficult to obtain in wells.

The basic conditions that control the availability of water in the earth (groundwater) are natural and fixed. Skillful well design, construction, and management are extremely important factors in obtaining satisfactory amounts of groundwater, but these factors apply at any potential well site only if natural geologic conditions favor the type of supply desired. For example, even the most elaborate and careful well construction does not obtain a groundwater supply for a large city at a site where all the earth formations to great depths are dense, tight materials which do not allow water to flow into the well.

Northeastern Illinois has geologic conditions that make it one of the most favorable areas in the State for obtaining groundwater. Farm supplies from shallow sources are readily available in much of the area. Municipal and industrial supplies are widely available from deep sources and are also locally available from shallow sources.

The purpose of this report is to provide general information on the availability of groundwater in nine counties: Cook, DuPage, Grundy, Kane, Kankakee, Kendall, Lake, McHenry, and Will. This region has an area of some 5000 square miles and a population of over 5,250,000. It includes densely populated

2

and industrialized sections, such as Cook County, and sparsely populated agricultural districts. Evaluation of the groundwater possibilities within the region, therefore, has taken into consideration both domestic and large-scale demands.

This report is based on a study of the nine counties by six members of the Groundwater Division of the Illinois State Geological Survey: Robert E. Bergstrom, Merlyn B. Buhle, John W. Foster, James E. Hackett, Wayne A. Pryor, and Lidia F. Selkregg. It is the second of a series prepared to assist in watersupply improvement on the farms of Illinois.* The Geological Survey is cooperating in this program with the extension services of the Agricultural Engineering Department, University of Illinois. The region covered here is Agricultural Extension District 1, eastern part. We hope this report will improve the general understanding of groundwater occurrence and assist in the procurement of suitable groundwater supplies.

The authors are happy to acknowledge the generous assistance given in this study by many drilling contractors of northeastern Illinois and by members of the State Water Survey, particularly W. B. Millis of Chicago.

GEOLOGY OF THE REGION

The main features of the northeastern Illinois landscape were developed during the geologically recent past, when great continental glaciers covered much of northern United States. From centers of snow accumulation in Canada, these vast ice sheets advanced southward, as well as in other directions. They scraped the land surface over which they moved, picked up and transported rock debris, and deposited most of the debris at the melting outer borders of the ice.

The glacial deposits, called drift, form an irregular surface blanket that covers the solid layered bedrock in northeastern Illinois. In excavations, such as quarries and road cuts, and in deeply eroded stream valleys, the drift mantle has been removed and the underlying bedrock exposed. In most of the area drilling penetrates varying thicknesses of unconsolidated glacial material before striking bedrock. Not only the deposits themselves but the form of some of the deposits were produced by glacial processes. For example, the prominent ridges that parallel Lake Michigan in McHenry, Lake, Kane, Cook, DuPage, and Will counties are thick accumulations of mixed clay, silt, sand, pebbles, and boulders heaped up along the front of a melting glacier. These ridges are called moraines. Cook, Grundy, and Kankakee counties contain wide flat areas which were the sites of shallow glacial lakes. Some valleys of northeastern Illinois have broad sand and gravel flats which were built up by large streams fed by the melting glaciers.

Because the great glaciations of the Ice Age occurred quite recently in geologic time, the landscape of northeastern Illinois is actually fairly young.

An older landscape - carved in the bedrock largely before the glaciers advanced

^{*} The first report, Water Wells for Farm Supply in Central and Eastern Illinois, by John W. Foster and Lidia F. Selkregg, has been issued by the Illinois State Geological Survey as Circular 192, and is available free of charge from the Survey in Urbana.

into the area - would be found if the mantle of drift were stripped away. Despite its burial beneath glacial deposits which locally attain a thickness of several hundred feet, the bedrock surface is not entirely beyond our range of study. Thousands of water wells drilled through the glacial drift into the bedrock provide detailed information on the bedrock topography. The bedrock surface has hills and valleys just as the land surface does. Some surface valleys coincide with valleys in the bedrock, but in areas of very thick drift the surface and buried valleys may not correspond.

In contrast to the complex, heterogeneous glacial deposits, the bedrock formations present a more orderly picture. They consist of layers of limestone, shale, and sandstone arranged one upon the other like the pages of a thick book. Although they are firm, dense rocks now, they were originally deposited as loose sediments in shallow seas which invaded the continent. They were buried and hardened into solid rock during the several hundred million years after the seas had retreated from northeastern Illinois. The rocks were later gently tilted from their original horizonal position, so that today they dip southeastward 10 to 15 feet per mile. The tilted beds are cut by the erosion surface beneath the glacial drift, producing rudely parallel belts that trend approximately north-south. In McHenry, Lake, Cook, DuPage, Will, and Kankakee counties, a limestone-like rock, called dolomite, underlies the glacial drift, whereas to the west bands of older shale and sandstone lie directly beneath the drift.

Beneath the 3000 or 4000 feet of layered rocks is ancient crystalline rock which forms the basement. The crystalline rock is mainly granite as shown by a few very deep wells in Illinois. Crystalline basement rock is at the surface today in the St. Francois Mountains of Missouri and the Black Hills of South Dakota where there has been marked uplift and deep erosion of the overlying stratified rock.

WATER IN THE EARTH

Water that occurs in the ground and comes to the surface in springs and wells has long been regarded as somewhat mysterious. The details of its occurrence, source, quantity, quality, temperature, pressure, and movement are complex, but the general principles pertaining to groundwater are relatively simple and well understood.

Water falling on or flowing over the ground seeps through openings between loose particles of the soil and percolates downward. Below a certain depth, all openings in the loose surface material (such as glacial drift) and in the underlying bedrock are filled with water. This water occurs in pores between grains and in rock crevices, and not in streams or lakes (except only locally in limestone caves). Because rainfall continually contributes to or replenishes the supply, groundwater is a renewable resource.

The upper surface of the water-saturated zone is called the water table. Its position is shown by the depth at which water stands in shallow wells, borings, and excavations. It roughly parallels the surface topography, rising under the uplands and intersecting the ground surface along perennial streams, lakes, and swamps.

d I nada, They

the

rg-

ter-

of at

rift he rial

ok, 1,

₃ of by

g. anced

ili-

Water from the saturated zone is not everywhere available for withdrawal by wells, as this is controlled by the details of the local geology. A bed of clay may contain a large volume of water per cubic foot but hold the water so tightly that a well drilled into it may be "dry." On the other hand, a bed of pea gravel may contain less water per cubic foot than the clay, but the water in the gravel is not held and can move quite readily between the grains and into a well bore. As the well is pumped, more water flows in.

The problem involved in obtaining a groundwater supply, therefore, is to strike a "formation" that will transmit its water to the well bore. Most drilled wells that are "dry" are unsuccessful not because of lack of water in the rocks but because water-yielding (permeable) formations are not present.

A special word should be said about the geology of artesian wells. Water that occurs in some of the deep permeable sandstone formations underlying northeastern Illinois comes from rainfall, which enters these rocks some distance away, where they are close to the surface. Because relatively water-tight formations occur above the deep sandstones in northeastern Illinois, the water in the deep beds behaves somewhat differently from that in beds at shallower depths. It is under natural pressure and therefore may rise several hundred feet in a well that penetrates a deep sandstone. We call these wells artesian wells. In the days before the water from the deep sandstones was heavily exploited by industries and cities, some artesian wells flowed without pumping.

WATER-YIELDING FORMATIONS

The most important water-yielding deposits in the glacial drift above the bedrock are beds of clean, loose sand and gravel. They range from thin discontinuous streaks to extensive beds tens of feet thick. Drilled wells are usually productive where the sand and gravel is a few feet or more thick and water-bearing. Where only thin streaks of sand and gravel are present in otherwise tight glacial drift, large-diameter dug wells are generally the only way of obtaining groundwater from the shallow drift.

The grain size (texture) of sand and gravel deposits is extremely important in determining their water-yielding properties. Good water-yielding sands are coarser than sugar and nearly all the grains are the same size. The percentage of clay and silt in sand and gravel deposits should be low because this fine material occupies the spaces between the larger grains and slows water movement. Few natural deposits have the uniform coarse textures that are ideal; however, a skillful drilling contractor, familiar with sand and gravel well construction, can by proper design and development often make a satisfactory well in formations that are fine-grained or not uniformly sorted, or in formations that contain some clay and silt.

Much of the bedrock beneath the glacial drift in northeastern Illinois is a limestone-like rock called dolomite. Groundwater in limestone and dolomite occurs in fractures and in channels dissolved out of the rock. The success of a water well drilled in limestone or dolomite, therefore, depends upon the well bore actually penetrating water-filled joints and channels.

The thick dolomite in much of northeastern Illinois is well creviced and fractured, particularly in the upper part, so that it is an important source of

of cl tightly gravel gravel bore.

is to drilled rocks

Vater ing ne disters, the t shalral ells

thout

e the dise and in only -

porg sands pere this ater tre vel ttisor in

s is a mite ss of the well

and ce of groundwater. The dolomite is especially good for groundwater at the many places where it is overlain by drift containing substantial sand and gravel deposits. On the other hand, where the drift is tight and non-water-yielding, the underlying dolomite is also commonly "tight." Some drilling contractors substantially improve the performance of limestone and dolomite wells in the area by enlarging existing joints and channels with hydrochloric acid, which dissolves part of the rock with which it comes in contact.

Another important water-yielding rock of northeastern Illinois is sandstone. It occurs at a depth of several hundred feet and more throughout the area. In southwestern Kendall County an important water-yielding sandstone lies just beneath the glacial drift.

Water occurs in sandstone between the sand grains, just as it does in loose sand deposits. Therefore, the size and uniformity of the grains is extremely important. Sandstone also contains variable amounts of cement, which binds the grains together. The amount of cement is another factor that affects the water yield. Tightly cemented sandstones are not good formations for water unless they are well jointed or fractured, like limestones.

The deep sandstones of northeastern Illinois - the Galesville sandstone in particular - and the shallower St. Peter sandstone are good groundwater sources because they are uniform in texture and loosely cemented. Less satisfactory for groundwater are the fine-grained tightly cemented near-surface sandstones of the Pennsylvanian system ("Coal Measures") in Grundy County.

COOK COUNTY

Groundwater possibilities in sand and gravel beds in Cook County are best in the upland areas in the northwestern, south-central, and southern parts of the county. These water-yielding deposits are principally sand and fine to coarse gravel, which are in some places as much as 100 feet thick. They occur mainly in the lower half of the glacial drift. Best possibilities for industrial and municipal supplies of water in sand and gravel are near Elgin, Bartlett, Arlington Heights, and Orland Park; also locally elsewhere.

In central Cook County and along the Des Plaines River southwest of Summit, the glacial drift is thin and sand and gravel deposits are correspondingly thin or are absent. Here shallow sand deposits are mainly fine-grained or silty, and virtually all drilled wells penetrate solid bedrock for groundwater supplies.

The Chicago Plain lies generally east of Homewood, Oak Forest, Evergreen Park, Justice, LaGrange, Bellwood, Niles, and Northfield. This low-land is underlain by silts and clays deposited on the floor of ancient Lake Chicago. Water-bearing sands are extremely scarce in the lake beds. The surface of the Chicago Plain is marked with more-or-less continuous ancient beach ridges and spits of clean sand, for example, the Glenwood Beach running southeastward from Glenwood and the Wilmette spit fanning south-south-westward from Wilmette. The sands of these features are generally too thin to be suitable for water wells, but locally the sands extend to depths of 25 to 30 feet and are water-bearing in the lower part. A narrow band of beach sand along the present Lake Michigan shore yields groundwater to sand-point wells in scattered places.

The common source of groundwater for domestic wells in Cook County is in the upper part of the dolomitic bedrock, lying immediately below the drift. Beneath the silts and clays of the Chicago Plain in the eastern part of Cook County, the dolomitic bedrock is relatively tight and locally not water-yielding. Areas where the shallow dolomite is particularly favorable for water wells are in the western half of T.35 N., R. 14 E., near Chicago Heights, and in parts of Ts.38 and 39 N., R. 12 E., near LaGrange.

Cook County is underlain by deeply buried sandstone, a reliable source of municipal and industrial water supplies. The Galesville sandstone ranges in depth from 1000 feet in northwestern Cook County to 1800 feet in the extreme southeastern part. Most municipal and major industrial water supplies in the county are obtained from this aquifer.

In north-central Cook County, in the vicinity of Des Plaines, bedrock formations have been severely broken and displaced, or faulted (fig. 3). Uncommonly great thicknesses of shale are encountered locally within the Des Plaines faulted area, and dolomite formations may be thin or absent. Groundwater possibilities in dolomite are therefore poorer here than they are in most of Cook County.

DUPAGE COUNTY

Thick glacial drift containing water-yielding sand and gravel deposits overlies the dolomite in DuPage County. The most favorable areas for sand and generally over 175 feet thick. Sand and gravel beds are locally as much as 75 to 100 feet thick. Sand and gravel suitable as farm and domestic water sources are found in many places in the upper 75 feet of drift, but some of the deposits lie as deep as 200 feet.

In the western two-thirds of the county, groundwater supplies can be obtained locally from sand and gravel, but the possibilities of finding very favorable deposits are generally poorer than in the east. In the southwestern corner of the county the drift is less than 50 feet thick.

Groundwater generally can be obtained from open cracks and crevices in dolomite that lies directly below the glacial drift in most of the county. The dolomite is particularly well creviced along the Fox River north of McHenry and provides an excellent groundwater source. Shale beds are found below the drift along the western edge of the county and in T.43 N., Rs. 5 and 6 E. Because shale is generally tight and non-water-yielding, it is often necessary to drill into the underlying dolomite.

Deep water-bearing sandstone occurs throughout McHenry County. Depth to the top of the Galesville sandstone ranges from about 800 feet in the southwest to about 1100 feet along the eastern edge of the county.

WILL COUNTY


Farm and domestic supplies of groundwater in most of Will County are obtainable with wells 50 to 150 feet deep. Many of these wells obtain groundwater from sand and gravel beds within the glacial drift. Some wells penetrate through the drift and obtain water from open cracks and crevices in dolomite. Along the Des Plaines River and in extreme southern Will County, the dolomite lies at or near the surface, so water-yielding sands and gravels are scarce. Best possibilities for high-capacity wells in sand and gravel are in parts of T.36 N., R. 11 E., and T.34 N., R. 14 E., where the drift is generally over 100 feet thick and where widespread sand and gravel beds are known.

West of the DuPage River and along the Kankakee River in southern Will County, thick shale beds occur below the glacial drift at most places. Where these shales are non-water-yielding, wells must be deepened to penetrate dolomite at depths of 150 to 300 feet. South of Braidwood, in extreme southwestern Will County, sandstone beds of the Pennsylvanian system lie beneath 10 to 50 feet of glacial drift. These sandstones yield water to a number of farm and domestic wells, but they are not considered suitable for high-capacity wells.

Deep water-bearing sandstone occurs throughout Will County. Top of the Galesville sandstone lies at a depth of about 1300 feet in the northwest and about 1900 feet in the extreme southeast. Where sandstone lies deeper than 1000 feet below sea level, as in southeastern Will County, consideration should be given to possible poor water quality.

PLANNING HIGH-CAPACITY WELLS

Most areas in northeastern Illinois are underlain by one or more formations favorable for the construction of high-capacity water wells. The key to successful well construction in the region lies not so much in where the wells are located but how carefully the wells are adapted to the geology and hydrology.



INST "CTIONS TO DRILLERS

..ite Copy —
III. Dept. of Public Health
Yellow Copy — Well Confractor
Blue Copy — Well Owner

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, BUREAU OF ENVIRONMENTAL HEALTH, 535 WEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62701. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION.

ILLINOIS DEPARTMENT OF PUBLIC HEALTH WELL CONSTRUCTION REPORT

Seepage Tile Field	Sewer (non Cast iron)	Sewer (Cast iron)	Barnyard	Manure Pile	sed for human consumption?	•
Building & Ft.	Cess Pool	Privy	Septic Tank 50'	Leaching Pit	. Is water from this well to be used for human consumption?	Yes X No

	√ ∾			
7, 7, 7	d? Yes 🗲	Type	Depth of s	γ No
4. Date Well completed	5. Permanent Pump Installed? Yes 🗲	Manufacturer	Capacity gpm.	6. Well Top Sealed? Yes
ż	ĸ.			ø

8. Well Disinfected? Yes X No
9. Water Sample Submitted? Yes No

% N

Yes

Pitless Adaptor Installed?

REMARKS:

SECTION IN SECTION OF PLAT DEPTH OF BOTTOM 200 4g 6 65 above ground level. Pumping level 60 ft. when pumping at 10 3 8 WOHS - DATE 11-37-79 GEOLOGICAL AND WATER SURVEYS WELL RECORD THICKNESS 5 5 ריו dra Date 6-13-2 License No. 23 I Well No. To (FI.) Twp. 35.4 Rge. 13E 6 Static level 40 ft. below casing top which is 13. County_ و techenes Elev. Sec. (CONTINUE ON SEPARATE SHEET IF NECESSARY) From (Ft.) FORMATIONS PASSED THROUGH 1120-NSF 2.87/69 1 hedule 40 P.U.C. inestora Kind and Weight Rich at depth 68 to 145 ft. Size Hole below casing:_ 7967 ft. Slot_ Casing and Liner Pipe hours. mestone Screen: Diam._ Property owner. Water from______ Permit No. _ Address __ Length:_ gpm for _ Phane Driller SIGNED __ ē. (Jr.) 9 ∞.

> IDPH 4.065 10-72 KNB-1

INSTRUCTI' TO DRILLERS

Copy—

Iv. Dept. of Public Health
Yellow Copy — Well Contractor
Blue Copy — Well Owner

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, BUREAU OF ENVIRONMENTAL HEALTH, 535 WEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62701. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION.

ILLINOIS DEPARTMENT OF PUBLIC HEALTH WELL CONSTRUCTION REPORT

Drive Pipe Diam. 5 in. Depth 125 ft. Drive Pipe Diam. 5 in. Depth 57 ft. Finished in Drift Gravel Packed	TO (Ft.)
Hole Diam. 5 in. Buried Slab: Yes ipe Diam. 5 in. Ide in Drift. In.	PROM (Pt.)
, i i	(KIND)
ater!	a. Glone:

	Seepage Tile Field 75'	Sewer (non Cast iron)	Sewer (Cast iron)	Barnyard	Manure Pile	
Distance to Negrest:	Building 25 Ft.	Cess Pool	Privy	Septic Tank 50'	Leaching Pit	

consumption?		
s water from this well to be used for human consumption		8-15-78
g from this well to	% V	ate well completed
3. Is watę	Yes	4. Date w

7 Yes No	Type	Depth of setting	X No
stalled		gpm.	Yes
5. Permanent Pump Installed? Yes_	Manufacturer	Capacity gpm.	6. Well Top Sealed? Yes X
က်			6

8. Well Disinfected? Yes X No 9. Water Sample Submitted? Yes No

7. Pitless Adaptor Installed?

REMARKS:

4.065		_
	10-72	KNB-

GEOLOGICAL AND WATER SURVEYS WELL RECORD

10.		owner Dennis Rogel	St.	Well No.	-
	Driller	Charles Fy	License	No. 23	
Ξ		No. 77899	Date 8-8	-78	
12	-	Lime	13. County	, W111	
	at denth	Formation the 57 to 125 ft.	Sec.	0/19	E
14.	_	Diam.	Twp	35N	
		ft. Slot	Rge.	12E	
7.	Casing	r and Liner Pine	Elev	 	×
ā	15		From (Pt.) To	To (Pt.)	SHOW
<u> </u>	511		-	_	ION PI
				∀	Je J n
ل				_	
16.		Size Hole below casing: 5	_in.		
17.		Static level 45 ft. below casing	ig top which is.	is +1	; i
	above	above ground level. Pumping level 50	J.	ft. when pumping at	1 at 10
	gpm for _1	r 1 hours.			•
18.		FORMATIONS PASSED THROUGH	н	THICKNESS	DEPTH OF BOTTOM
		Clày		104	104
		Gravel		171	571
		Limestone		189	1251
1					
[
}					
Ō	ONTINO	(CONTINUE ON SEPARATE SHEET IF NECESSARY)	NECESSARY)		
SIG	SIGNED S	M.C. Million	RABA DATE	Dec.	20, 1978

TO DRILLERS INSTRUCTIC

III. Dept. of Public Health Yellow Copy ~ Well Contractor Blue Copy – Well Owner

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, BUREAU OF ENVIRONMENTAL HEALTH, 535 WEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62701. DO NOT DETACH GEOLOGICAL/WATER SURYEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION.

GEOLOGICAL AND WATER SURVEYS WELL RECORD

PUBLIC HEAL	REPORT
DEPARTMENT OF	CONSTRUCTION
ILLINOIS DEI	WELL

		•	
. Hole Diam. 5 in. Depth 125 ft. Burled Slab: Yes No Drive Pipe Diam. 5 in. Depth 63 ft. Finished in Drift In Rock X Gravel Packed	TO (Ft.)		
ole Diam. 5 ir nried Slab: Yes. e Diam. 5 in. In Drift	FROM (Ft.)		
Bored Hole Diam. Burled Slai Drive Pipe Diam. Finished in Drift.	(KIND)		
1. Type of Well a. Dug Bored_ Curb material b. Driven c. DrilledX Tubular	i. 00m:		

2. Distance to Nearest: Building 71. Cess Pool	Seepage Tile Field 75 Sewer (non Cast Iron)
Privy Septic Tank 50'	Sewer (Cast iron) Barnyard
Leaching Pit	Manure Pile

- Is water from this well to be used for human consumption? ٩ Yes
 - 8-8-18 Date well completed
- å Type_ Depth of setting. Yes Permanent Pump Installed? _gpm. Manufacturer_ Capacity
 - Yes Well Top Sealed?
- S_N Yes Well Disinfected? Yes__ Pitless Adaptor Installed?
- Š Yes 9. Water Sample Submitted?

HEMARKS:

1DPH 4.065 KNB-1 10-72

1. Permit No. 71757 Date 8-3-18 1. Screen: Diam.	10.	_	John Gallag		Well No. 1	
Sec. 1757 Date 8-3-78		Address Driller	Charels Fykes	'		
Section Limestone 13. County Will	11.		77757			
Sec. 61/f	12.					
Signature Sign		at depth	to 125	Sec.	_	
Single	14.			Twp.	35N	
Elev. Rind and Weight From (FL.) To (FL.) A-53 15 1bs. 0 63 A-53 15 1bs. 0 A-54 A-55 A-54 A-55 A-54 A-55 A-54 A-55 A-55 A-55 A-54 A-55 A-54 A-55 A-54 A-55 A-54 A-55 A-54 A-55 A-54 A-55 A-55 A-55		Length:		Rge.	12E -	
Hole below casing: A-53 15 1bs. 0 63'	. 15	Casing	and Liner Pipe	Elev	<u> </u>	
Hole below casing: A-53 15 1bs. 0 63' 25' 15' E below casing: 5 in. It level 60 ft. below casing top which is +1 It level 60 ft. below casing top which is +1 It level 20 10' 10' It level 20' 20' 20' Clay 20' 20' 20' Cravel 43' 63 Cravel 43' 63 It mestione 62' 125 It lest if necessary 125 Chanklad 3' 125 Chanklad 4' 125 Chanklad 5' 12	Ē	am. (In.)	pue	$\overline{}$		
Hole below casing: it level 60_ft. below casing top which is +1 ve ground level. Pumping level 70_ft. when pumping at 10 if or 1 _ hours. FORMATIONS PASSED THROUGH Clay Clay Gravel Limestone 62' 125' NUE ON SEPARATE SHEET IF NECESSARY CATCHER 19	Ш	5"	53 15			FION PLAT
Hole below casing: it level 60 ft. below casing top which is +1 ve ground level. Pumping level 70 ft. when pumping at 10 if or 1 hours. FORMATIONS PASSED THROUGH Clay Clay Gravel Limestone 62' 125' Limestone NUE ON SEPARATE SHEET IF NECESSARY OTHER MATCH 28, 19		-			1	
lic level 60 ft. below casing top which is +1 ve ground level. Pumping level 70 ft. when pumping at 10 for 1 hours. FORMATIONS PASSED THROUGH Clay Clay Gravel 43' 63' Limestone 62' 125' Limestone 62' 125' Limestone 62' 125' DATE March 28, 19' Chankly Barky Date March 28, 19'	ي ل					
ve ground level. Pumping level 70 ft. when pumping at 1 for 1 hours. FORMATIONS PASSED THROUGH THICKNESS BEPT 20 20 20 20 20 20 20 20 20 20 20 20 20	17.		60 ft. below	ng top which	is +1	ا
FORMATIONS PASSED THROUGH Clay Clay Gravel Limestone 62' 125 Limestone NUE ON SEPARATE SHEET IF NECESSARY) Chankly I I I I I I I I I I I I I I I I I I I		above gr gpm for	Pumpin 1.	el 70 ft. w	hen pumping	2
Clay 20° 20° 20° 20° 20° 20° 20° 20° 20° 20°	E E	FO	PASSED	H	THICKNESS	DEPTH O
Gravel 43' 63 Limestone 62' 125 NUE ON SEPARATE SHEET IF NECESSARY Chanles Gravel Date March 28.			Clay		201	20
Limestone 62' 125 NUE ON SEPARATE SHEET IF NECESSARY Chanles I Barge 18.			Gravel		431	631
NUE ON SEPARATE SHEET IF NECESSARY Chanles I I A RELE March 28.			Limesto	ie	621	1251
NUE ON SEPARATE SHEET IF NECESSARY Chanlas Barch 28.	١					
NUE ON SEPARATE SHEET IF NECESSARY LINGARD BAREL DATE MARCH 28.	ı	-	-			
NUE ON SEPARATE SHEET IF NECESSARY CARALLA DAGAL DATE MATCH 28.	į					
NUE ON SEPARATE SHEET IF NECESSARY CARALLAL BAREL DATE MARCH 28.	1					
NUE ON SEPARATE SHEET IF NECESSARY) CARALLA DA PLA DATE MATCH 28.	I					
NUE ON SEPARATE SHEET IF NECESSARY SAGNAL DA PARA DATE MAICH 28.	İ					
JONANAM CINTER DATE March 28.	2	ONTINUE	ON SEPARATE SHEET IF	NECESSARY		1
	SIG	NED /	WIND THANK	DATI	E_March	1

III. ... of Public Health Yellow Copy – Well Contractor Blue Copy – Well Owner

INSTRUCTIONS TO DRILLERS

EQUESTED AND MAIL ORIGINAL TO STATE JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. FILL IN ALL PERTINENT INFORMATION

ILLINOIS DEPARTMENT OF PURILY HEALTH

נ	Hole Diam. 5 in. Depth 40 ft. Buried Slab: Yes No lipe Diam. in. Depth ft. ed in Drift in Nock A	TO (Ft.)		
TION REPORT	Hole Diam. 5 in. Burled Slab: Yes 'ipe Diam. in. id in Drift Pucked	FROM (Ft.)		
WELL CONSTRUCTION REPORT	Drive F Finish	(KIND)	Puttings	
WEL	ype of Well Dug Bored Curb material Driven Tubular	Grout:		

,	Seepage Tile Field 75	Sewer (non Cast iron)	Sewer (Cast Iron)	Banyard	Manure Pile
. Distance to Nearest:	Building Ft.	Cess Pool	Privy	Septic Tank 50	Leaching Pit

- Well furnishes water for human consumption? Yes λ Date well completed_
- Capacity 20 gpm. Depth of Setting Permanent Punp Installed? Yes. Well Top Sealed? Yes_ Manufacturer 188 <u>ئ</u> ق
 - odel Number Pitless Adapter, Installed? Yes_ How attached to casing? Well Disinfected? Manufacturer 💪
 - Type Disinfected? Pressure Tank Size da gal. Pump and Equipment _ocation __
- 11. Water Sample Submitted? REMARKS:

GEOLOGICAL AND WATER SURVEYS WELL RECORD

18	3-79	16					SHOW
& Spreadle Well No.	License No. 10.	13. County Lead	Sec. 6.70.	Twp. 35 77	Hge. (9.6.	Liev.	From (Ft.) To (Ft.)
	d kniegim	Pormation	at depth 45_ to 140_ft.	Diom. in.	п. элог	15. Casing and Liner Pipe	Kind and Weight F
10. Property owner Address	Driller (Zh. 11. Permit No	12. Water from	at depth	14. Screen: Diam.	rengtu:	15. Casing c	Diem. (in.)

SHOW	SECTION PLAT	SE SW SW	Dr.W. 44.220	3	impling at 20
To (Ft.)	89			, 1	when pu
From (Ft.) To (Ft.)	0			In.	1 20 II.
Find and Weight	Leh 40			ole below casing:	above ground level. Pumping level 20 ft. when pumping at 20
Diem. (in.)	5			16. Size Ho	above g

18. FORMATIONS PASSED THROUGH	THICKNESS	DEPTHOF
Las	0	3
oley,	E	15
Land & Granel	5/	61
Clad ,	61	50
dand Sanel	50	63
Lach	63	146
CONTINUE ON SEPARATE SHEET IF NECESABLY		

- DATE. EET IF NECESSARY) SIGNED 4

Milta Copy — III. Dept of Public Health Yellow Copy T Well Centracion Blue Copy — Well Owner

INSTRUCTIONS TO DRILLERS

JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 335 WEST

ILLINOIS DEPARTMENT OF PUBLIC HEALTH WELL CONSTRUCTION REPORT

<u>.</u>			i	7.	
	Hole Diam. 5 in. Depth 11.	Drive Pipe Diam. In. Denth	In Rock	. Cravel Packed	- (.) (+ - (.)
	ole Diem.	uried Slat e Dlam.	In Drift.	CKO	
	p	Drive Pip	Finished in Drift	. Urdvei Packed	
1. Type of Well	Des	Driven	c. Drilled X	d. Grout:	
 	Ġ	نم	ij	4	
~					

	(KIND)	FROM (FL.)	TO (Ft.)	
	Outtonso	0	29	
	0			•
Distance to Neaest:	rest:			
Building	25 Ft.	Seepage Tile Field 75	1d 75	
Cess Pool		Sewer (non Cast Iron)	(non)	
Prim		Sewer (Cast iron)		
Septic Tank		Barnyard		

Seepage Tile Field 75 Sewer (non Cast Iron) Sewer (Cast Iron)	Barnyard Manure Pile	m consumption? Yes X No	Yes X Date No
Building 35 Ft. Cess Pool	Septic Tank Leaching Pit	3. Well furnishes water for human consumption? Yes X No_A. Date well completed	5. Permanent Pump Installed? Yes X Date

	Manufacturer Type Location 11/2//
	Capacity 10 gpm. Depth of Settling Ft.
ග්	Well Top Sealed? Yes X No Type Will Lanne
	Pilless Adapter Installed? Yes X No
	Manufacturer 18.02.
	How attached to casing? Por I Aux
.	8. Well Disinfected? Yes X No
oi Oi	9. Pump and Emilyment Dieinfacted? Vac A.

nfected? Yes K No	es No 3859
Equipment Disir	11. Water Sample Submitted? Yes REMARKS.

	-
	C
	C
	1
	RFCO
-	ш
	S WELL
	_
	_
	11
	SWELL
	VEYS
	~
	L
	>
	Œ
	=
	R SURVEYS
	~
	-
	بىي
	-
	AND WATER S
	=
	CAL
	_
	CICAL
	7 1
	\simeq
	77
	$\boldsymbol{\varkappa}$
	ب
	EOLOC
	GEO
	7.5
	*
	Ç

10. Prope Addr	10. Property owner JUDGES INCHES, Well No. 171.	0,10	Well No.	Charles Charles
Drille	Driller Rod Wieller Lord License No. 102-0020	Licens	No. /	17/0000-50
11. Perm	Permit No. OCO478	Date 3-10-88	3-10	-88
12. Water	Water from Age &	- 13. County 200K	11y - CL	OOK
ap p	at depth to ft.	Sec.	Sec. 31.7h	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
14. Scree	14. Screen: Dlam. ln.	Twp.	Note	F
Length: _	th: ft. Slot	Rge .	12E	I
		Elev.		
15. Casir	15. Casing and Liner Pipe			
Diam. (In.)	Kind and Weight	From (Ft.) To (Ft.)	To (Ft.)	M OH!
b	Black stul	Ø	62	SECTION PLAT
				86,85,10

NEID NELL	/ impling at 10
29	ch is
Q	in. ng top which
Black Stul	16. Size Hole below casing: 5 in. 17. Static level 15 ft. below casing top which is 1. above ground level. Pumping level 10. 9pm for 10.
3	16. Size H 17. Static above

18. FORMATIONS PASSED THROUGH	THICKNESS	PROTTING
Cloy	>	7
Sand + gravel	69	62
Rock	811	281
		·
(CONTINUE ON SEPARATE SHEET IF NECESSARY)		

(X/) DATE. SIGNED KWELLES LONG

IDPH 4.065

INST TYTONS TO DRILLERS

Yellow Copy - Well Contractor Blue Copy - Well Owner War Dout, of Public Health

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. GEOLOGICAL AND WATER SURVEYS WELL RECORD

LUCALA STWELL No.

WOLK

Driller Fakk Permit No. Water from Less

Property owner Address 129

10.

License No.

Sec. L

at depth 65 to 100 ft.

12.

Screen: Diam. Length:

14

13. County

Date _6

Rge / Twp.

ft. Slot

Elev. _

1. Type of Well a. Dug Bored Hole Diam. in. Depth ft. Curb material Buried Slab: Yes No b. Driven Drive Pipe Diam. in. Depth ft. C. Drilled Finished in Drift in. In Rock

1				
اسا				
Distance to Newest:			0	
Building 25	Ft.	Seepage Tile Field	ld & C	
Cess Pool		Sewer (non Cast iron)_	iron)	
Privy Santic Tonk / 6		Sewer (Cast iron) _ Rannyard		
Leaching Pit		Manure Pile		
Well furnishes water for hyman consumption? Yes	ater for hyman s	consumption? Ye	ss No	
Date well completed 6/5/26	eted - 15/15/	96		
Permanent Pump Installed? Yes LDate	Installed? Yes	Date	No	
Manufacturer	Tyr	TypeLocation	ion	
Capacitygpm. Depth of Setting	gpm. Depth of	Setting #0	Ft.	
Well Top Sealed? Yes / No_	? Yes No.	Type		
Pitless Adapter Installed? Yes	Installed? Ye	s / No	1	

above ground level. Pumping level 40 ft. when pumping at 40

Static level 10_ft. below casing top which is_

Size Hole below casing:

16.

SHOW LOCATION IN SECTION PLAT

To (Ft.) 157

From (Ft.)

Kind and Weight

Diam. (in.)

Casing and Liner Pipe

15.

	SS DEPTH OF	10	15	63	1,40	•		
	THICKNESS	01	5	25	75			
gpm far Z hours.	18. FORMATIONS PASSED THROUGH	VEHOW CLAY	BLOF CLAY	ا, ا	KIME STOOVE			

Model Number

Type 1 Yes

_gal.

Pressure Tank Size

Yes

Water Sample Submitted?

REMARKS:

Location _

Pump and Equipment Diginfected?

Yes

Well Disinfected?

യ് ഗ് 0

How attached to casing?

Manuíacturer_

. 6.

DATE.

SIGNED

(CONTINUE ON SEPARATE SHEET IF NECESSARY)

III. Depl. of Public Health Yellow Copy - Well Contractor Blue Copy - Well Owner

ERS INSTRUCTIONS TO D'

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION.

שביו אבווט זכן ומנוט THINDS DEPARTMENT OF

	Ξ		. =	=======================================		-	-			22 I	
ILLINOIS DEFARIMENT OF FUBLIC HEALTH WELL CONSTRUCTION REPORT		Type of Well a. Bored Hole Dlem. 5 in. Depth 900 (1.		b. Driven X . Drive Pipe Diam. in. Depth (1.	c. Drilled Finished in Drift In Rock X	Tubular . Gravel Packed	1 (m)	(KIND) FROM (PI.) TO (PI.)	aithras		

Distance to Nearest:	Test:	
Building	F.	Seepage Tile Field 75
Cess Pool		Sewer (non Cast iron)
Privy		Sewer (Cast fron)
Septic Tank 50	0	Barnyard
Leaching Pil		Monure Pile

Model Number Pump and Equipment Disinfected? 12 gal. Manufacturer KLEELLAIN Pitless Adapter installed? How allached to casing?_ Yes. Well Disinfected? 9. 0

11. Water Sample Submitted? REMARKS: CLEEN TO

Maccarled

Location _

Pressure Tank Size_

Ownermal

(CONTINUE ON SEPARATE SHEET IF NECESSARY)

SIGNED

GEOLOGICAL AND WATER SURVEYS WELL RECORD

Well No Well No 1944 (19	To (FL) LOCATION IN SECTION PLAT	thich is / It. when pumping at AU. THICKNESS DEPTHOF	3 70	63 800	
Address 1923 42. 410 (all) Address 1925 42. 410 (all) Driller 100 100 Date Water from 1900 11. Count at depth 10 to 200 11. Sec.	Length: It. Slot Rge. Casing and Liner Pipe March Role Prom (Pt.) March Role Prom (Pt.)	16. Size Hole below casing: 7.70 in. 17. Static level 40 ft. below casing top which is above ground level. Pumping level 60 ft. when gpm for 4 hours. 18. FORMATIONS PASSED THROUGH	Plast.	Lock Strand	

Scoy - Tru, Dayl, of Public Health Yellow Copy - Well Contractor Blue Copy - Well Owner

JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. FILL IN ALL PERTIMENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST

ILLINOIS DEPARTMENT OF PUBLIC HEALTH ֚֚֡֝֜֝֝֡֜֜֝֝֝֜֜֝֓֓֓֓֓֓֓֓֓֓֡֜֜֜֓֓֡֓֜֜֜֜֜֜֓֓֡֓֡֡֜֜֜֜֡֡֡֓֜֜֜֜֡֡֡֡֜֜֜֜֡֡֡֡֡֜֜֜֡֡֡֡֡

ILLINOIS DEPARTMENT OF PUBLIC HEALTH WELL CONSTRUCTION REPORT	GEOLOGICAL AND WATER SURVEYS WELL RECORD	CORD
	10. Property owner Lott P 1 45 414 SA Well No.	
	Warr Kel	
a. Dug Bored Hole Diam. in. Depth ft.	License No L	B-66
Curb material Burled Slab: Yes No	11. Permit No. 4 6/24 Date 6/14/	7
Drive Pipe Diam.	Water from Moest	POR
c. Drilled Finished in Drift In Rock	motion of the state of the stat	
Tubular Gravel Packed		
d. Grout:	Length: # Slot	
	15 Coging and Liner Pine	
		MOHS
	pul X	LOCATION IN
	8 A-53 Sec. 0 65	SECTION PLAT
o Newest:)C 20. 10
Ft. Seepage lile Fie		
100		
	Size Hole below c	4
130	17. Static level 1. below casing top which is	± (!
Leaching Pit Manure Pile	above ground level. Pumping level 10 It. when pumping at	ping at 152
Well furnishes water for human s	gpm for Lours.	
Date well completed 1/4 1/6	10 FORMATIONS PASSED THROUGH	ESS DEPTH OF
5. Permanent Pump Installed? Yes Date No		_
Manufacturer Type Location	VELLOW ChAY	0/0
Capacity gpm. Depth of Setting PC Ft.	177	-
6. Well Top Sealed? Yes No Type	10 Stor 25 10	100
Pitless Adapter Installed? Yes L	CARVEL & BOUNDERS HIA 45	10.0
Manufacturer Model Number		-
How attached to casing?	A/M 43/026	120
Well Disinfected? Yes No		
Pump and Equipment Disinfected? Yes		
10. Pressure Tank Size Legal. Type		
# page		
11. Water Sample Submitted? YesNo		
REMARKS:		

1DPH 4.065 1/74 - KNB-1

(CONTINUE ON SEPARATE SHEET IF NECESSARY)

SIGNED

.

Whit. Apy III. Dopt. of Public Health
Yellow Copy -- Well Contractor
Blue Copy -- Well Owner

INSTRUCTIONS DRILLERS

JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST

GEOLOGICAL AND WATER SURVEYS WELL RECORD

PUBLIC HEALTH	REPORT
DEPARTMENT OF PU	CONSTRUCTION R
LINOIS DEPA	WELL C

	Hole Diam. 5 in. Depth 240 ft.	In. Depth ft.		TO (Ft.)			
WELL CONSTRUCTION REPORT	le Diam. 5 in	~	cked	FROM (Ft.)			
L CONSTRUC		Drive P	. Gravel Packed	(KIND)	Cuttings	P	
WEI	1. Type of Well a. Dug Bored.	Curb material b. Driven c. Drilled	Tubular				

	Seepage Tile Field 25 Sewer (non Cast iron) Sewer (Cast iron) Barnyard Manure Pile consumption? Yes No
Cutturgs	Distance to Newest: Building Cess Pool Cess Pool Sever (non Cast iron) Privy Settic Tank Leaching Pit Manure Pile Manure Pile Well furnishes water for human consumption? Yes No

4. Date well completed

121 \mathcal{Z}

sted? Yes / No	1. Type gallu.	O = O	es No
9. Pump and Equipment Diginfected? Yes	10. Pressure Tank Size Xis gal. Type 90 Lt	Location (Lead Care Mal	11. Water Sample Submitted? Yes No

Well Disinfected? Yes_

oursel metructed to do so. REMARKS:

Permit book = DRDR DE De hour contract 165

(CONTINUE ON SEPARATE SHEET IF NECESSARY)

SIGNED

LOCATION IN SECTION PLAT BOTTOM above ground level. Pumping level 800 ft. when pumping at THICKNESS S. a 10% 62/ Well No. From (Ft.) To (Ft.) <u>り</u>ろ _ License No. _ Static level 30 ft. below casing top which is Sec. 13. Counly Twp. Rge. Elev. . Date -FORMATIONS PASSED THROUGH Kind and Welght at depth 50 to 240 ft. Size Hole below casing: Length: ft. Slot. Casing and Liner Pipe gpm for 4 hours. Screen: Diam. Property owner Permit No. _ Water from_ Address ___ Driller ___ Dluta. (In.) インの 10. 15. 12. 14. ₩.

10PH 4.065 1/74 - KNB-1

111. Dest. o , c Health Yellow Copy – neil Contractor Blue Copy – Well Owner

FILL IN ALL PERTINEIT INFORMATION REQUES AND MAIL ORIGINAL TO STATE OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 MEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO'NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION,

ILLINOIS DEPARTMENT OF DIPLIFUELT

•					
neal in T	in. Depthftftftft.	. In Rock	TO (Ft.)		
TION REPOR	Ϋ́		FROM (FL.)		
WELL CONSTRUCTION REPORT	Drive P		(дын)	-	
TEM.	a. Dug. Bored Curb material	C. Drilled Tubular			•

	Seepage Tile Field 5.5	Sewer (non Cast Iron)	Sewer (Cast iron)	Barnyard
2. Distance to Newest:	Building 30 Ft.	Cess Pool	Privy	Septic Tank R
~	•			

٠	Yes - No		No
Manure Pile	man consumption?	1.4/52	Les Lorte
Leaching Pit	3. Well furnishes water for human consumption? Yes No	4. Date well completed 62.4/22	5. Permanent Pump Installed? Yes - Date
	က	÷	ស

Location	1202 Ft.	Гуре	No	Model Number
Manufacturer	Capacity gpm. Depth of Setting 1222	6. Well Top Sealed? Yes No	7. Pitlezs Adapter Installed? Yes	
		_	•	

9. Pump and Equipment Disinfected? Yes No	0. Pressure Tank Sizegal. Type	
_	4	
Ē		i
쓨	ij	- 1
ğ	6	.
<u>=</u>	- 1	1
ž	- 1	
_	- [
ē	26	
ď	Š	
Ē	뇓	ı
й	Ţ	1
덛	•	Location
B	Ħ	30
읕	88	20
3	ä	ŏ
5	o.	

Well Disinfected? Yes 6 How attached to casing?_

æ

Į	1	
I	å	
	YesNo	
	Submitted?	
	Sample	
	Water S	RFMARKG
	11	C

GEOLOGICAL AND WATER SURVEYS WELL RECORD

.0	99-20	Jook .						BECTION PLAT	200	CE SE SEN	
が がご Well No.	License No. 122-66.	- 13. County Good	Sec. 251 /4	Twp. 366	Elev.		From (Ft.) To (Ft.)	27 0			
10. Property owner ANN BANK. Address 125 - AT N. 110 AVE	Driller FORE H Sans	Water from Ross	at depth 25 to black.	. Screen: Diam. In. Length: It. Slot		15. Casing and Liner Pipe	Kind and Welght	A-53 6020			
10. Propert Addres	Driller 11. Permit	12. Water f	· at dept	14. Screen: Diam.	•	15. Casing	Dlam. (In.)	10			

THICKNESS	BOTTON	
3	l's	
20	26	
0/	کی	
35	8	
را	25	
110	185	
	CKNRBSS 20 20 20 20 20 20 20 20 20 20 20 20 20	

(CONTINUE ON SEPARATE SHEET IF NECESSARY) SIGNED A INST. MONS TO DRILLERS

White Cooy — III, Dayl, of Public Health Yellow Cooy — Well Contractor Blue Copy — Well Owner

FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURYEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION.

ILLINOIS DEPARTMENT OF PUBLIC HEALTH WELL CONSTRUCTION REPORT

11. 12. 13. 15. 15. 15. 15. 15. 15. 15. 15. 15. 15	6.7.	28.			
a. Dug. Bored Hole Diam in. Depth 302ft. Curb material Buried Slab: Yes No b. Driven Drive Pipe Diam in. Depth ft. c. Drilled X Finished in Drift In Rock X Tubular Gravel Packed To (FL.) d. Grout: (KIND) FROM (FL.) TO (FL.)	2. Distance to Nearest: Building Ft. Seepage Tile Field Sewer (non Cast iron) Sewer (Cast iron) Septic Tank Burnyard	pleted /0 mp Installed? Ye mp Installed? Ye mp. Depth of	Well Top Sealed? Yes No Type Pitless Adapter Installed? Yes Model Number How attached to casing?	9. Pump and Equipment Disinfected? Yes No 10. Pressure Tank Size gal. Type Location	MARKS: Overler instructed

₽ .	404.12			LOCATION IN BECTION PLAT	_	1 at ft.	DEPTHOF	7	30	80	280			100	
WELL RECO	Cra	12 12 12 12 12 12 12 12 12 12 12 12 12 1		To (F1.)	<u> </u>	hich is ft. when pumping at	THICKNESS	0	1	30	03			6/01	
owner Grand Maien sunvers	Driller 1964 Filtering License N. Driller 1964 Filtering No. 11. Permit No. 10 6.5 9 Date 10. Water from 12. Water from	at depth to fi. Sec. 22 14. Screen: Diam. th. Twp. 2 Length: ft. Slot Rge. 4	15. Casing and Liner Pipe	Dism. (in.) Kind and Weight Prom (Pt.) To	16. Size Hole below casing: 43/3 in.	Static level ft. below casing top wabove ground level. Pumping level	gpm for bours.	X	Chart	Mariel	Bank			(CONTINUE ON SEPARATE SHEET IF NECESSARY) SIGNED THE	

Yellow Copy - Wall Contractor I. Deol. of Public Health Blue Copy - Well Owner

INSTRUCTIONS TO SIGLERS

JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION. FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST

ILLINOIS DEPARTMENT OF PUBLIC HEALTH

7	•	Qft.	Zn. 1:	-	П		
—	-	n. Depth 20	Depth 11	in nock	TO (Ft.)		
TION REPOR		Hole Diam. 5 in. Depth 2001t.	. 4		FROM (Ft.)		
WELL CONSTRUCTION REPORT		j	;	Gravel Packed	(KIND)		
WEL	1. Type of Well	a. Dug Bored	b. Driven	Tubular	d. Grout:	·	
	-						

	Distance to Newest:	1 44 Ft. Seepage Tile Field 95		Sewer (Cast iron) 56	Septic Tank 89 Barnyard	
-	Distanc	Building	Cess Pool	Privy _	Septic 1	

O FILT SIT STORY	Some (and Continue)	Sewer (Cast iron) 56	Barnyard	Manure Pile	Well furnishes water for human consumption? Yes X No
Building 4th Co		Privy	Septic Tank 89	Leaching Pit	t. Well furnishes water for humo

- Permanent Pump Installed? Yes X. Date 924/80 No 11 Manufacturer_Sta-Rite_Type_Sub_Location_ Capacity_11_gpm. Depth of Setting_100 Date well completed _9/23/80.
- -No Type Water tight cap. Monufacturer Baker Monitor Model Number How attached to casing? Clamp on type Pitless Adapter Installed? Yes X Well Top Sealed? Yes X
 - Pump and Equipment Disinfected? Yes X No. Well Disinfected? Yes X No.
- Pressure Tank Size_42_gal. Type_Conventional Location Basement <u>.</u>
 - Yes_ 11. Water Sample Submitted? REMARKS:

GEOLOGICAL AND WATER SURVEYS WELL RECORD

_	10.	Proper	10. Property owner ANDREW MACK		Well No.	
_		Addres	Address 179th & 104th Ave, Orland Park, Illinois	Ave. Orl	and Park, Illi	nois
		Driller	Driller J. R. STINNETT	License No.	e No. 102-106	, ,
	11.	Permit	11. Permit No. 96142	Date	Date 9/16/80	, ,
	12.	Water	Water from Linestone	13. Com	13. County COOK	, 1
		at dep	at depth 112 to 200 ft.	Sec.	29,78	
	14.	Screen	14. Screen: Diam. in.	Twp.	3	т
		Length	Length: ft. Slot	Rae	121	7
		•		Flav		-7
	15.	Casing	15. Casing and Liner Pipe			,
	ā	Dlem. (in.)	Kind and Weight	From (Ft.) To (Ft.)	_	_
		۲"	Steel 15/	0	117 SECTION PLAT	<u> </u>
					いくいろがく) .
	<u>.</u>	Size H	16. Size Hole below casing: 5	in.		
,	17.	Static	17. Static level 65 ft. below casing top which is	ing top whic	in is	نے

above ground level. Pumping level 65 11. when pumping at 200 gpm for 2

18. FORMATIONS PASSED THROUGH	THICKNESS	DEFTH OF BOTTOR
Black dirt top soil	2	2
Generally clay with small rock 79	79	81
Mostly gravel with some sand	33	114
itravel and lots of sand	. (درر
Limestone		202

(CONTINUE ON SEPARATE SHEET IF NECESSARY)

DATE Dec. SIGNED

INSTRUCTIONS TO F

III. Depl. of Public Health Yellow Copy — Well Centractor Dive Copy - Well Owner

DEPARTMENT OF PUBLIC HEALTH, CONSUMER HEALTH PROTECTION, 535 WEST JEFFERSON, SPRINGFIELD, ILLINOIS, 62761. DO NOT DETACH GEOLOGICAL/WATER SURVEYS SECTION. BE SURE TO PROVIDE PROPER WELL LOCATION, FILL IN ALL PERTINENT INFORMATION REQUESTED AND MAIL ORIGINAL TO STATE

્ર ≍	i '	=:	:	Ξ		5 1	9
			· ·	_	-,-		
-	Denth	in Denth	. In Rock X		TO (M.)		
WELL CONSTRUCTION REPORT	Hole Diam. In Danth	Buried Slab: Yes		cked	FROM (FIL.)		
CONSTRUC		Drive	Finished in Drift	ranger Lag	(AIND)		
	1. Type of Well a. Dus . Bored	b. Driven	c. Drilled X	d. Grout:	- 		
		**					

	Seepage Tile Field + 75	Sewer (non Cast Iron)	Sewer (Cast iron)	Banyard	Monure Pile	consumption? Yes. No.
DANGE CO INCIDENCE	Building do Ft.	Cess Pool	Privy	Septic Tank +50	Leaching Pit	Well furnishes water for human consumption? Yes

-ffer	0.44	Ft		•	
12 Ver X Dute /7-16	'pe Location	Setting	Type	es X No	Model Number
4. Date well completed 5. Permment Pumplingthalogy	Manufacturer Letter Type Location	Capacity 12 april Depth of	Well Top Sealed? Yes No	Pitless Adapter Installed? Y	Manufacturer Meditary Model Nu
ئى ئ	;		ශ්	7:	

% ₽ Pump and Equipment Disinfected? 12 bestoner 16 gal. How attached to casing? Well Disinfected? Yes__ Pressure Tank Size Location _ வ் ஜ்

11. Water Sample Submitted? Yes. REMARKS

GEOLOGICAL AND WATER SURVEYS WELL RECORD

11	02-177 /86 ook			AOH	BECTION PLAT	98th, 124	37
Well No. Mokena, IL	8/22/2	Sec. 29. Twp. 36N Rge. 12E		To (m.)	18		
ards Rd., N	License No. 102. Date 8/22/86. 13. County Gook	Sec. Twp.	Elev.	From (Ft.) To (Ft.)	•		
10. Property owner Jeff Richards Address 19326 S. Wolf Rd.	Driller Frank Sharpe Permit No. 126416 Weter from Linestone	th <u> </u>	and Liner Pipe	Kind and Weight	ASTM AS3 B		
10. Proper	Driller 11. Permit 12. Water 1	at dep(14. Screen Length	15. Casing	Diam. (In.)	>		
10. Property owner Address 193	Driller Frank 11. Permit No. 120 12. Woter from Lin	or depth 10 to 14. Screen: Diam. Length: ft.	15. Casing and Liner Pipe		S ASTM		-

.ft. when pumping at_ _ft. below casing top which is_ above ground level. Pumping level_ 16. Size Hole below casing:_ bours. 17. Static level ___ gpm for

١	PODULTIONS BASED SUBSTICE		
او	CONTAINED FASSED INKOUGH	THICKNESS DEPTH	BOTTON
	Clar	8	8
.	l bod	13	20
	Clary	53	73
	Broken Gravetone	7	01
	linestone	00/	03/
1			
			ı.
NCC	CONTINUE ON SECTION OF THE PROPERTY OF THE PRO		

- DATE. HEET IF NECESSARY) CONTINUE ON SEPAN SIGNED L